

OnSight PROS Report Professional Documentation http://www.onsightpros.com

The Attached Report is performed by Property Reports On Sight, LLC Certified Field Inspectors and thus should not be confused with an inspection performed by Licensed Real Estate Commission Inspectors. This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. Certified Field Inspectors are not licensed to check the mechanicals, plumbing, or electrical units in a home and therefore this report will not reflect any issues or functionality of those components. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report.

4/16/2014 10:49

AM Inspector: Tech 1

CUSTOMER NO.: 654321 St.


Address: 123 Main St.

City: Any City

ST: USA


Zip Code: 12345

Type of Inspection: Periodic Report




If no safety issues or deficiencies observed NO COMMENTS will be Made.






Exterior Comments:

 Walls-All Around-Separation and cracks across left side front left wall hardy board siding. Separation and cracks across right side front left all hardy board siding. Separation and cracks across left side of front right wall hardy board siding. Separation and cracks across right side of front right wall hardy board siding.
 Lawn-Grass-Further attention needed to strengthen grass growth off Front Yard.











Walls/Paint

5



Door Stops

4/16/2014 11:15:28 AM CAM



Walls/Paint

6

 Dining Room 1. Flooring 2. Walls/Paint 3. Light Fixture 4. Blinds/Drapes 5. Windows 6. Ceiling Fan 7. Outlet/Switch Covers 8. Door Stops 9. Overview 10. Ceiling 11. 2nd Dining Room 12. Other 	Observed		Further Evaluation	Dining Room Comments:
1 4/16/2014 11:11:26 AM CAM			2	4/16/2014 11:11:32 AM CAM
<image/>			Flooring	
3 4/16/2014	11:11:38 AM	1 CAM	4	4/16/2014 11:11:45 AM CAM
Ceiling				

4/16/2014 11:11:50 AM CAM



Walls/Paint

5











Kitchen 1. Flooring 2. Walls/Paint 3. Ceiling 4. Light Fixtures 5. Blinds/Drapes 6. Kitchen Counter/Back Sp 7. Sink/Faucet 8. Cabinet Under Sink 9. Garbage Disposal 10. Refrigerator 11. Range/Oven 12. Dishwasher 13. Oven 14. Door Stops 15. Overview 16. Lower Cabinets 17. Upper Cabinets 18. Windows 19. Other			Further Evaluation	Kitchen Comments:
1 4/16/2014 11:17:16 AM CAM			2	4/16/2014 11:17:24 AM CAM
		Flooring		










Hallway / Stairway Comments:







2nd Hallway Comments:


4 . Outlet/Switch Covers-Broken outlet cover in front of AC closet.





Bedroom Comments:







11 4/16/2014 12:00:32 PM CAM

2nd Bedroom Comments:

8 . Door Stops-Missing doorstop to Closet Door.






<page-header><page-header><page-header><page-header><page-header>

3rd Bedroom Comments:

8 . Door Stops-Missing doorstop behind Bedroom door.





11 4/16/2014 12:00:46 PM CAM


4th Bedroom Comments:


9 . Smoke Detector-Outdated smoke detector replaced by newly installed hard-wired unit at existing unit spot on ceiling surface.

Bathroom 1 . Flooring 2 . Walls/Paint 3 . Ceiling/Exhaust 4 . Light Fixtures 5 . Blinds/Drapes 6 . Window 7 . Sink/Faucet 8 . Cabinet Under Sink 9 . Shower Faucet 10 . Tub/Faucet 11 . Commode 12 . Towel Racks 13 . Door Stops 14 . Overview 15 . 2nd Bathroom 16 . 3rd Bathroom 17 . Half Bath 18 . Other		Image: A state of the stat	Evaluation Bathroom Comments: 2 . Walls/Paint-Small indentation a
1 4/16/201	4 11:27:43 AM CA	AM 2	4/16/2014 11:27:49 AM CAM

Overview

Flooring






Bathroom Comments:

2 . Walls/Paint-Small indentation across wall surface from Bathroom door knob hitting it.

 2nd Bathroom 1. Flooring 2. Walls/Paint 3. Ceiling/Exhaust 4. Light Fixtures 5. Blinds/Drapes 6. Window 7. Sink/Faucet 8. Cabinet Under Sink 9. Shower Faucet 10. Tub/Faucet 11. Commode 12. Towel Racks 13. Door Stops 14. Overview 15. 2nd Bathroom 16. 3rd Bathroom 17. Half Bath 18. Other 	Observed		Further Evaluation	2nd Bathroom Comments:
14/16/2014 11:30:22 AM CAMImage: Image: Ima			2	4/16/2014 11:30:27 AM CAM






10 4/16/2014 11:31:31 AM CAM

Half Bathroom 1 . Flooring 2 . Walls/Paint 3 . Ceiling/Exhaust 4 . Light Fixtures 5 . Blinds/Drapes 6 . Window 7 . Sink/Faucet 8 . Cabinet Under Sink 9 . Shower Faucet 10 . Tub/Faucet 11 . Commode 12 . Towel Racks 13 . Door Stops 14 . Overview 15 . 2nd Bathroom 16 . 3rd Bathroom 17 . Half Bath 18 . Other	Observed		Further Evaluation	Half Bathroom Comments:
1 4/16/2014	+ 11:16:9 AM (CAM	2	4/16/2014 11:16:17 AM CAM










Garage Comments:

1 . Flooring-Main floor view obstructed by tenants vehicle.





Miscellaneous Comments:

2 . Window Screens-Tears in window screen in lower left middle window on rear back wall. Missing screen door on rear sliding glass door.

3. Water HeaterGas or Electric-Electric powered State Select.

4 . Water Heater MFG Date-Not present.

5. AC Filter-AC filter not present in unit.


9. Smoke Detector-Outdated smoke detectors replaced by newly installed hard-wired units. Date on back of outdated units read the year 2002Jan08. All units are functional after testing with liquid smoke. Date on backs of new hard-wired units read 2014Feb24. Total of 6 units were installed.

10 . Smell Test-Clean smell throughout property, no signs of tobacco use or pet odor inside property.

12 . Carpet Wear-Overall carpet wear in quality shape throughout property.







Backyard Comments:

2 . Fence-Outward lean left side of rear right fence line. Slight inward lean right side of rear back fence line. Slight inward lean left side of rear back fence line. Inward lean right side of rear left fence line. Broken vertical wood slat right side of rear left fence line. Deterioration along bottom of right side wood slats on rear left fence lines broken vertical wood slats midsection of rear left fence line. Broken vertical wood slat left side of rear left fence line. Broken vertical wood slat on front left fence line.

9. Rear Gate-Rear gate on front right fence line does not close properly.